


SAMPLE ROOF DRAWING



(A) Failure in wall flashing



(B) Water entering at blister



(C) Excessive ponding area

Legend

	Control Joint		Expansion Joint
<u>Roof Top Units</u>			
	HVAC on Curb		Skylight
	Roof Hatch		Unit on Curb
	HVAC on Sleepers		Unit on Sleepers
<u>Projections</u>			
	Plumbing Stack		Hot Stack
	Pitch Pan		Metal Sleeve Stack
<u>Drainage</u>			
	Drain (Existing)		Scupper
	Drain (New)		
<u>Miscellaneous</u>			
	Gas Line		Crickets
	Walkway		Roof Level Change
	Paver Walkway		Core Test
<u>Problem Indicators</u>			
	Blister		Ridging
	Ponding		Bare Spot
	Flashing Problem		Photo Indicator

* Note: -U indicates an unused item

ECS Roofing Co.

3920 West Hawthorn Court, Waukegan, IL 60087
Tel: (847) 970-4500 Fax: (847) 918-8000

Project		Project Name Here	
Customer		Customer Name Here	
DWG. By		JIM	
Date	July 27, 2012	Scale	N.T.S

This drawing is the property of ECS Roofing Co.
It may not be reproduced without consent.